



South Creek Flood Study

Volume 2 – Figures

Job Number W4749
Prepared for Lake Macquarie City Council
April 2011



Cardno Lawson Treloar Pty Ltd

ABN 55 001 882 873 Level 2 910 Pacific Highway Gordon NSW 2072

Australia

Telephone: 02 9499 3000 Facsimile: 02 9499 3033 International: +61 2 9499 3000

cltnsw@cardno.com.au www.cardno.com.au

Document Control

Version	Status	Date	Author		Reviewer	
1	Preliminary	14/10/2009	Andrew Reid	AR	Rhys Thomson	RST
2	Draft	28/2/2010	Andrew Reid	AR	Rhys Thomson	RST
3	Draft for Exhibition	22/4/2010	Andrew Reid	AR	John Tilley	JRT
4	Final Draft	21/6/2010	Andrew Reid	AR		
5	Preliminary Final	23/8/2010	Andrew Reid	AR		
6	Final	6/4/2011	Andrew Reid	AR	Rhys Thomson	RST

6 April 2011

[&]quot;© 2011 Cardno Lawson Treloar Pty Ltd All Rights Reserved. Copyright in the whole and every part of this document belongs to Cardno Lawson Treloar Pty Ltd and may not be used, sold, transferred, copied or reproduced in whole or in part in any manner or form or in or on any media to any person without the prior written consent of Cardno Lawson Treloar Pty Ltd."

List of Figures

Figure 1.1	Catchment Locality
Figure 2.1	Floodplain Management Process [in Volume 1]
Figure 3.1	South Creek Catchment
Figure 4.1	Questionnaire Responses
Figure 4.2	Land-use Zones
Figure 5.1	Model Extent
Figure 5.2	1D Network
Figure 5.3	Elevation Grid
Figure 5.4	Roughness Layout
Figure 5.5	RAFTS Model Subcatchments
Figure 5.6	Hydrographs – Node E01
Figure 5.7	Hydrographs – Node A08
Figure 5.8	Hydrographs – Node B02
Figure 5.9	Hydrographs – Node FB01
Figure 5.10	June 2007 Observed Flood Levels
Figure 5.11	1990 and 1988 Event Responses
Figure 5.12	Rainfall Station Locations
Figure 5.13	Rainfall Depth at Eleebana Gauge June 2007
Figure 5.14	June 2007 Event – Rainfall Comparison
Figure 5.15	June 2007 Event – Spatial Distribution
Figure 5.16	June 2007 Event – Pluviograph Record
Figure 5.17	February March 1990 Event – Rainfall
Figure 5.18	February March 1990 Event – Rainfall
Figure 5.19	April 1988 Event – Rainfall
Figure 5.20	April 1988 Event – Rainfall
Figure 5.21	Marmong Point Water Level June 2007
Figure 5.22	Marmong Point Level – February March 1990
Figure 5.23	Marmong Point Level – April 1988
Figure 5.24	June 2007 Event and Design Intensities

6 April 2011 ii

South Creek Flood Study Prepared for Lake Macquarie City Council

Figure 5.25	June 2007 Event – Peak Depth
Figure 5.26	June 2007 Event – Peak Water Level
Figure 5.27	Creek Profile and Reference Locations
Figure 5.28	June 2007 Event – South Creek Water Level Profile
Figure 5.29	Flow Hydrographs – James Street
Figure 5.30	Flow Hydrographs – Sanctuary Grove
Figure 5.31	Flow Hydrographs – Burton Road
Figure 5.32	Flow Hydrographs – Warners Bay Drive (near Burton Road)
Figure 5.33	Flow Hydrographs – Warners Bay Drive (near Jonathan Street)
Figure 5.34	Flow Hydrographs – Downstream of Jonathan Street
Figure 5.35	June 2007 Event - Depth-Time Graphs
Figure 6.1	Reference Locations
Figure 6.2	1% AEP Critical Duration
Figure 6.3	Peak Water Level - PMF
Figure 6.4	Peak Water Level – 0.5% AEP
Figure 6.5	Peak Water Level – 1% AEP
Figure 6.6	Peak Water Level – 2% AEP
Figure 6.7	Peak Water Level – 5% AEP
Figure 6.8	Peak Water Level – 10% AEP
Figure 6.9	Peak Water Level – 20% AEP
Figure 6.10	Peak Water Level – 50% AEP
Figure 6.11	Peak Depth - PMF
Figure 6.12	Peak Depth – 0.5% AEP
Figure 6.13	Peak Depth – 1% AEP
Figure 6.14	Peak Depth – 2% AEP
Figure 6.15	Peak Depth – 5% AEP
Figure 6.16	Peak Depth – 10% AEP
Figure 6.17	Peak Depth – 20% AEP
Figure 6.18	Peak Depth – 50% AEP
Figure 6.19	Peak Velocity - PMF
Figure 6.20	Peak Velocity – 0.5% AEP
6 April 2011	<u></u> i

iii 6 April 2011


South Creek Flood Study Prepared for Lake Macquarie City Council

Figure 6.21	Peak Velocity – 1% AEP
Figure 6.22	Peak Velocity – 2% AEP
Figure 6.23	Peak Velocity – 5% AEP
Figure 6.24	Peak Velocity – 10% AEP
Figure 6.25	Peak Velocity – 20% AEP
Figure 6.26	Peak Velocity – 50% AEP
Figure 6.27	Water Level Profile – South Creek
Figure 6.28	Water Level Profile – Tributary
Figure 7.1	Blockage Assessment – Water Level Difference 1% AEP
Figure 7.2	Blockage Assessment – Water Level Difference 5% AEP
Figure 8.1	Provisional Hazard Classification [in Volume 1]
Figure 8.2	Provisional Hazard - PMF
Figure 8.3	Provisional Hazard – 1% AEP
Figure 8.4	Provisional Hazard – 5% AEP
Figure 8.5	Provisional Hazard – 20% AEP
Figure 9.1	Hydraulic Category - PMF
Figure 9.2	Hydraulic Category – 1% AEP
Figure 9.3	Hydraulic Category – 5% AEP
Figure 9.4	Hydraulic Category – 20% AEP
Figure 10.1	Houses Inundated Above Floor Level
Figure 11.1	Climate Change Assessment – Water Level Difference 0.4m Lake Level Rise
Figure 11.2	Climate Change Assessment – Water Level Difference 0.91m Lake Level Rise
Figure 11.3	Climate Change Assessment – Water Level Difference 0.91m Lake Level Rise and 30% Rainfall Increase
Figure 11.4	Climate Change Assessment – South Creek Profile 0.4m Lake Level Rise
Figure 11.5	Climate Change Assessment – Tributary Profile 0.4m Lake Level Rise
Figure 11.6	Climate Change Assessment – South Creek Profile 0.91m Lake Level Rise
Figure 11.7	Climate Change Assessment – Tributary Profile 0.91m Lake Level Rise


6 April 2011

















Cardno Lawson Treloar W4749\V4 August 2010

FIGURE 4.2 LANDUSE ZONES









FIGURE 5.2 SOUTH CREEK 1D NETWORK





SOBEK MODEL - ELEVATION GRID









FIGURE 5.4 ROUGHNESS LAYOUT




RAFTS MODEL SUBCATCHMENTS





























































Intensity - Frequency - Duration Data













FIGURE 5.25 PEAK DEPTH - JUNE 2007 EVENT















W4749\V4 August 2010 **FINAL**


South Creek Flood Study




W4749\V4 August 2010 FINAL

South Creek Flood Study


FIGURE 5.28C June 2007 Event Water Level Profile





























June 2007 Event - Depth-Time Graphs



Cardno Lawson Treloar W4749\V4

August 2010

FINAL

FIGURE 5.35 June 2007 Event -Depth-Time Graphs







FIGURE 6.1 REFERENCE LOCATIONS










FIGURE 6.3 PEAK WATER LEVEL - PMF






FIGURE 6.4 PEAK WATER LEVEL - 0.5% AEP






FIGURE 6.5 PEAK WATER LEVEL - 1% AEP






FIGURE 6.6 PEAK WATER LEVEL - 2% AEP








FIGURE 6.7 PEAK WATER LEVEL - 5% AEP















FIGURE 6.10 PEAK WATER LEVEL - 50% AEP



South Creek Flood Study









FIGURE 6.12 PEAK DEPTH - 0.5% AEP











FIGURE 6.14 PEAK DEPTH - 2% AEP










FIGURE 6.16 PEAK DEPTH - 10% AEP






FIGURE 6.17 PEAK DEPTH - 20% AEP






FIGURE 6.18 PEAK DEPTH - 50% AEP






FIGURE 6.19 PEAK VELOCITY - PMF






FIGURE 6.20 PEAK VELOCITY - 0.5% AEP






FIGURE 6.21 PEAK VELOCITY - 1% AEP






FIGURE 6.22 PEAK VELOCITY - 2% AEP






FIGURE 6.23 PEAK VELOCITY - 5% AEP






FIGURE 6.24 PEAK VELOCITY - 10% AEP






FIGURE 6.25 PEAK VELOCITY - 20% AEP








FIGURE 6.26 PEAK VELOCITY - 50% AEP



Cardno Lawson Treloar W4749\V4 August 2010


FINAL

FIGURE 6.27A
South Creek Flood Study
South Creek Water Level Profile





FINAL

FIGURE 6.27B South Creek Water Level Profile






















































FIGURE 10.1 HOUSES INUNDATED ABOVE FLOOR LEVEL





PEAK WATER LEVEL DIFFERENCE FOR LAKE RISE 0.4m
















FINAL


South Creek Flood Study



FINAL

South Creek Flood Study





FINAL

South Creek Flood Study

FIGURE 11.7 North Tributary Water Level Profile